



# Important!

Please give copies to all  
your VW Technicians

# Technical Bulletin

Subject: Spark Plug Connector, Using Proper Removal Tool

Group: 28

Number: 00-01

Model(s): All with 5 cyl. (eng. code AAF & ACU)  
All with VR6 (eng. code AAA & AES)

Date: July 14, 2000



## Condition

Spark plug connectors or ignition wires damaged by not using the correct tool for removal.

## Service

Whenever spark plug connectors or ignition wires must be removed:

- ◀ – Always remove using spark plug connector tool number T10029.

### **CAUTION!**

**Damage can occur to connectors or ignition wires by pulling ignition wires off by hand or by using incorrect tools such as 3277 or 3277A.**

### **Note:**

*Tools 3277 and 3277A were discontinued and Dealers were advised that these tools were to be scrapped via: Tools - Equipment Service Circular V98-09 dated 13-Nov-98.*

*Warranty claims for spark plug connectors or ignition wires found to be damaged by pulling ignition wires off by hand or by using an incorrect tool will be rejected.*