



# Technical Bulletin

Subject: **NEW Airbag WARNING! Labels**

Group: **00**

Number: **97-02**

Model(s): **All USA**

**1997** ▶



Date: **Mar. 12, 1997**

## Production

Beginning Feb. 25, 1997 production **ALL** vehicles will be equipped with NEW Airbag WARNING! labels.

All port facilities will assure that the labels are installed on the vehicles prior to shipment to the Dealer.

## Label Location



### **WARNING!**

**Installation of Airbag WARNING! labels is mandated by the Federal government to warn drivers and occupants of possible danger!**

**Labels may NOT be removed except as noted!**

**Fines may be assessed on non complying vehicles**

◀ New labels are located on either side of sunvisor mirror (sunvisor flipped down) as shown.

◀ A new label is located on sunvisor (sunvisor flipped up) as shown.

### **Note:**

**Sunvisors ordered through the Parts System will have labels installed.**

(Cont. on page 2)



# Technical Bulletin



◀ A new WARNING! label is attached inside at the center of windshield with the bottom edge of the label resting on the dash.

**Note:**

***This WARNING! label must also be in place when vehicle is delivered to the customer. ONLY THE CUSTOMER MAY REMOVE IT!***

Additional quantities of this label may be ordered using **Part No: 7D0 010 229J**.

**CAUTION!**  
***Part numbers are for reference only. Always check with your Parts Dept. for the latest parts information.***

**Service**

Prior to delivery to customer, assure that all Airbag WARNING! labels are in place.